


— Positive Wire
— Ground Wire
— AC Wire – Already attached to devices



Battery charger comes with cables ending in clamps. Find connectors to attach to these clamps and solder the connectors wire coming from power pole connectors.

Ring Terminals
 Connectors are indicated where needed. All other components are assumed to be connected via direct soldering of wires.

Wire Size Key
— 4 Gauge Wire
- - - 14 Gauge Wire
. . . 18 Gauge Wire

